Appl.No. 10/708,304
Amdt. Dated March 20, 2006
Reply to Office Action of 20 September 2005
Replacement Sheet





FIG. 1



3/4 One shot SW1 **₩** V ref 2 THR DCGH RST DCGH 7 TRIGGND DCGH Oscillator Lm4041 **C**6 U2a <u>~</u> > Ø LM5560 20 DCHG RST 1C THR 12 OUT CTRLV 12 3 C87 **R7** R16\$ R15 Coupling 13 OUT Level defect ∞ Appl.No. 10/708,304
Amdt. Dated March 20, 2006
Reply to Office Action of 20 September 2005 0 ന R5 >> Replacement Sheet VR1 **R**6 **[**] **R**2 Buffer \Box Piezo Sensor **%**≥1

Appl.No. 10/708,304
Amdt. Dated March 20, 2006
Reply to Office Action of 20 September 2005
Replacement Sheet




FIG. 1